



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

MASAYOSHI FUKATSU ET AL.

Appl. No.: 10/622,474

Filed: July 21, 2003

For: SHEET CONVEYING APPARATUS,
SHEET POST-PROCESSING APPARATUS,
AND IMAGE FORMING APPARATUS
PROVIDED WITH SHEET CONVEYING
APPARATUS AND IMAGE FORMING
APPARATUS

U.S. Patent No.: 6,988,730 B2

Issued: January 24, 2006

Examiner: David H. Bollinger

Group Art Unit: 3653

May 5, 2006

**Certificate
MAY 10 2006
of Correction**

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

05/08/2006 SZEWDIE1 00000055 6988730

01 FC:1811

100.00 CP

MAY 10 2008

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Lawrence A. Stahl
Attorney for Patentees
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

MAY 10 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,988,730 B2

DATED : January 24, 2006

INVENTOR(S) : MASAYOSHI FUKATSU ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 25, "arrange" should read --arranges--.

COLUMN 8:

Line 36, "down stream" should read --downstream--.

Line 60, "is" should read --are--.

COLUMN 9:

Line 66, "loner" should read --longer--.

COLUMN 11:

Line 15, "and the" should read --and--.

Line 46, "sheets" should read --sheet--.

Line 62, "jerkily, there" should read --jerkily. There--.

COLUMN 12:

Line 32, "upward" should read --upward of--.

COLUMN 14:

Line 7, "descend" should read --descent--.

COLUMN 15:

Line 59, "when said sheet conveying guide" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,988,730 B2

No. of add'l. copies
@ 30¢ per page



MAY 10 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,988,730 B2

DATED : January 24, 2006

INVENTOR(S) : MASAYOSHI FUKATSU ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18:

Line 14, "in" should read --in a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,988,730 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)
(Form#30)



MAY 10 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,988,730 B2

DATED : January 24, 2006

INVENTOR(S) : MASAYOSHI FUKATSU ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 25, "arrange" should read --arranges--.

COLUMN 8:

Line 36, "down stream" should read --downstream--.

Line 60, "is" should read --are--.

COLUMN 9:

Line 66, "loner" should read --longer--.

COLUMN 11:

Line 15, "and the" should read --and--.

Line 46, "sheets" should read --sheet--.

Line 62, "jerkily, there" should read --jerkily. There--.

COLUMN 12:

Line 32, "upward" should read --upward of--.

COLUMN 14:

Line 7, "descend" should read --descent--.

COLUMN 15:

Line 59, "when said sheet conveying guide" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,988,730 B2

No. of add'l. copies
@ 30¢ per page



MAY 10 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,988,730 B2

DATED : January 24, 2006

INVENTOR(S) : MASAYOSHI FUKATSU ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18:

Line 14, "in" should read --in a--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,988,730 B2

No. of add'l. copies
@ 30¢ per page



MAY 10 2006